



**Greene County
Regional
Airport Authority**

140 N. Valley Rd.
Xenia, Ohio 45385

Phone: (937) 376-8107
Fax: (937) 376-3807
Cell: (937) 231-5027

August 9, 2017

Windemere Homeowners Association
PO Box 341182
Beavercreek, OH 45434

Dear Mr. Simmons,

Thank you for reaching out to me regarding your concerns of noise levels near the airport. Rest assured, the Airport Authority takes all issues seriously.

I had a meeting to discuss these concerns with airport supervisors, and have made the following recommendations to our Fixed Base Operator (FBO) here at the airport. They are in charge of both the flight school and US Air Force AAL programs, which encompass a significant amount of our air traffic:

- When departing Runway 25 (towards the west) climb runway heading to pattern altitude before making turns on course. We have signs to this effect in our lobby and pilot briefing room. Note, however, this is not always possible due to winds, ceilings, density altitudes, and other flight conditions.
- In no-wind or crosswind conditions, when runway selection is completely discretionary to the pilot, use Runway 7 (departs to the east) if practicable.
- While the airport is open 24/7/7, make an effort to avoid lower altitudes and high throttle during dark hours over our housing area neighbors. I have provided them with aerials depicting sensitive areas.
- Adhere to the FAA published traffic patterns and approach plates.

The PAPI approach indicator will be relocated when the runway is extended to support the new corridor. It will likely increase in angle; however this is governed by FAA safety mandates and not in our control.

Thank you again for contacting me, and let me know if I can be of further assistance.

Respectfully,

Dave Kushner
Airport Manger